

Plant, Property, and Equipment Report

October 21, 2025

The irrigation system required additional work from Angel Oak. Pressure was still low and it was recommended we clean the intake pipe. Thanks to Gary Dreher and his Kayak for cleaning the intake pipe. Pressure improved but was still not satisfactory. Angel Ock changed the back flow valve on the intake pipe and then did an inspection of the entire system including repairing sprinkler heads that were clogged from pond debris. The system is now fully operational and programed for the watering schedule recommended for the new plants.

End of Report